

[illegible]

Product #: D139-799-029

Product Name: Hinged Fuel Cap

[illegible]

Issues: Adhesive used on the cap is not holding. The plastic hinge is too weak and is prone to break easily. The hinge allows the cap to contact the fuselage. The height of the hinge causes the hinge to contact the interior of sliding door. The kit doesn't protect the aircraft structure where the hinged cap contacts the fuselage.

Quarantine all stock of D5043-1/-3/-5/-041. At this time we should not sell any D139-799-029 Kits until advised otherwise by CS or engineering.

Reference NCR 17-6399 and customer service Case 9822, 9478, 7148, 9597 for details of the issues.
Please contact customer service or engineering with any questions.

Distribution:	VP Operations	Chief Engineer	Production Engineers	Purchasing Manager
	Director of Operations	Engineering Project Managers	Planning Manager	
	Director Quality Assurance	Engineering Clerk	Program Manager	
	Director of Engineering	Customer Support Manager	Technical Support	